

School Name: Patuxent Valley MS		Princip
IEQ Team Leader: Kim Mahle		I
LOOK-FORS	ROOM/LOCATION	
1. No unusual or offensive odors, or temperature discomfort	127	
2. No Air Fresheners	127,	
3. No food, dirty lunch boxes, etc. left in room	124, 120, 126, 135, 1098	
4. Vents are clean and unobstructed	Science storage, 115, 124, 119, 120, 122, 123, 125, 126, 127, 136, 135, 134, outside 129, 129, 128, 117, Storage outside staff lounge - dust in ceiling exhaust Science Storage Room, Kitchen Storage Room, Kitchen Office, Elevator Mechanical Room, S5, 174, Gym Storage Room-very high vents, Custodial Office, restroom and storageroom,	
5. Temperature sensors are not blocked	NA	
6. Area appears clean and dust free	115, 117, 121, vestibule outside 121 and 122, 126, Psych Office, media center, 110 Electric Room C2,	
7. No signs of animal infestation	NA	

School Name: Patuxent Valley MS		Principal
IEQ Team Leader: Kim Mahle		I
8. Ceiling tiles present; no broken, stained, or painted	vestibule to outside by rooms 121 and 122, 122, 123, 127, science storage, 115, 117, 118, 128, hall outside rm 129, vestibule outside 129, 164 (Storage), 109, Hall Exit by 109, 108, 106, 112, Science Storage Room Near 112, 114, Boys Restroom Imagination Blvd. 105,104, Computer Lab, Asst. Principal Office, Principal Office, Admin. Intern Office, Health Office, 145, Guidance Office, 1195, 1099 Kitchen Storage Room, S5, adult bathroom in girls locker room, restroom in girls locker room, Gym Office	
9. Walls show no signs of water damage/mildew/ paint irregularities	134, media center above staff lounge window, 128, Wall near room 145	
10. No condensation or other evidence of humidity on ceilings, walls, doors, etc.	Gym	
11. Limited use of non-issued HCPSS furniture and appliances	121, 122, 123, 125, 126, 124, , 129, Psych, 109, 108, 107, 110, Science Storage near 110, 111, 106, 105, Computer Lab, Guidance Counselor Office, Principal Office, Admin Intern Office, 101, 103, 145, 170, Gym Office	
12. No excessive fabric materials, stuffed animals, beanbags, pillows, etc.	107, 113, C115, 136, 102, 103, 145, 113, 116, 175	
13. No structural or physical gaps around exit doors	117 (fire door), vestibule outside 129	
14. No improperly stored materials/chemicals	127, 124, 128, 134, 111, 1098, Health Room	

School Name: Patuxent Valley MS		Principal
IEQ Team Leader: Kim Mahle		I
15. Floor coverings are level and secure (tile, carpets, wood board, etc.)	hallway outside media across from cafeteria doors	
16. Barrier mats vacuumed well	NA	
17. Fish tanks are clean and located away from vents/thermostats	NA	
18. Waterproof barriers in place for plants and no standing water	175	
19. Sinks and fountains drain quickly and work properly including absence of leaks	NA	
20. No standing water in sinks, fountains, on counter	NA	
21. Carpet dry nearby sinks, fountains	NA	
22. Soap and paper towels available	NA	
23. All electrical outlets secure, no frayed wires on equipment	Computer Lab	
24. All electrical cords secured and not extending across walkways	120, 121, 122, 110, 104, C115	

School Name: Patuxent Valley MS		Principal:
IEQ Team Leader: Kim Mahle		Inspector:
25. No extension cords used as permanent wiring	NA	
26. No electrical equipment near sinks or source of water	NA	
27. No exposed disconnected wires	NA	
ADJACENT SCHOOL GROUNDS		
LOOK-FORS	ROOM/LOCATION	
28. No litter	NA	
29. No large insect populations (wasps, bees)	NA	
30. Awnings secure, no leaks	NA	
31. Shrubbery not near vents or windows which can be opened	NA	
32. Trees do not provide access to roof	NA	
33. No broken windows	NA	
34. Windows are closed	NA	
35. Exterior doors are closed	NA	

School Name: Patuxent Valley MS		Principal:
IEQ Team Leader: Kim Mahle		Inspector:
36. No pools of standing/stagnant water	NA	
37. Exterior veneer intact	NA	
38. Outside lights working and intact	NA	
39. Gutters and downspouts clear/working	NA	
40. No stains from roof on outside walls	NA	
41. Bins from garbage and recycling clearly marked	NA	
42. Hard surfaces (sidewalks, etc.) cleared of any turf application	NA	
43. Proper maintenance of planted beds and other vegetation	NA	
44. Landscaping and turf look healthy and disease free	NA	
ADDITIONAL:		

IEQ SCHOOL DATA BASE	
al: Rick Robb	DATE: 12/14/16
EQ System Leader:	
COMMENTS	ADMIN
scented pine cones	x
	x
Teacher snacks/candy - need to be stored in plastic sealed container, Food	x
Furninure is blocking vent grilles, 117 - grille is broken and rattling noise coming from grille Science Storage Room - Return Air Grill Partially Blocked, Dusty or Dirty Vents,	x
NA	
Dust on counter tops and cabinets (general); in media - general dust but also dust above the windows to Jones' room - need a high crew 110-cobwebs Electric Room C2 Needs Sweeping	x
NA	

IEQ SCHOOL DATA BASE	
al: Rick Robb	DATE: 12/14/16
EQ System Leader:	
Many tiles with water damage, many are misfitted and/or have small holes on the tiles, tile grids bent in several locations (115), some missing tiles completely, Psyc/SLP Suite, Media Center, Staff Lounge, Storage outside staff lounge, 135,	
areas not completely painted, missing paint, water stain on wall near room 145,	
3 leaks	
lamps, fans, refrigerator, coffee pot, stool, microwave, lava lamps, chair	x
fake flowers, cushion on rocking chair, paper flowers, stuffed animals on cabinet tops, mobile hanging from ceiling, pillow, table cloth, rug, blanket, Room 113 & 116 - Flags	x
light getting in under door	
random bottles on white board ledges without labels Room 145 - chemicals Healthroom - Disinfectant Spray	x

IEQ SCHOOL DATA BASE

al: Rick Robb

DATE: 12/14/16

EQ System Leader:

broken floor tile

NA

NA

Plant missing water dish

x

NA

NA

NA

NA

Damaged Outlet

Need yellow extension cord cover for floor

IEQ SCHOOL DATA BASE

al: Rick Robb

DATE: 12/14/16

EQ System Leader:

NA

NA

NA

COMMENTS

ADMIN

NA

NA

NA

NA

NA

NA

NA

NA

IEQ SCHOOL DATA BASE

al: Rick Robb

DATE: 12/14/16

EQ System Leader:

NA

NA

NA

NA

NA

NA

NA

NA

NA

X (Construction)					
X (Construction)					
X (Construction)					
X (Construction)					

X (Construction)					
X					
X					

